| REPORT DOCUMENTATION PAGE | | | | | Form Approved |
|---|--|--|--|--|--|
| - | | | | | OMB No. 0704-0188 |
| maintaining the data needed, including suggestions for redu- Highway, Suite 1204, Adjusto | and completing and reviewing to ucing this burden to Department on VA 22202-4302 Responder | nis collection of information. Sen of Defense, Washington Headqu hts should be aware that notwiths | d comments regarding this burde parters Services. Directorate for h | en estimate or any nformation Operati w. no person shall | searching existing data sources, gathering and other aspect of this collection of information, ons and Reports (0704-0188), 1215 Jefferson Davis be subject to any penalty for failing to comply with a ADDRESS. |
| 1. REPORT DATE (DI | D-MM-YYYY) | 2. REPORT TYPE | | | 3. DATES COVERED (From - To) |
| 4. TITLE AND SUBTI | | Technical Papers | | | 5a. CONTRACT NUMBER |
| | | | | - | 5b. GRANT NUMBER |
| 6. AUTHOR(S) Case Sel Author(S) | | | | | 5c. PROGRAM ELEMENT NUMBER |
| | | | | | 5d. PROJECT NUMBER |
| | | | | | 5e. TASK NUMBER MIGQ |
| | | | | | 5f. WORK UNIT NUMBER |
| | | | | ĺ | 346120 |
| 7. PERFORMING OR | GANIZATION NAME(S) | AND ADDRESS(ES) | | | 8. PERFORMING ORGANIZATION REPORT |
| Air Force Research Laboratory (AFMC) | | | | | nei Oni |
| AFRL/PRS 5 Pollux Drive | | | | | |
| Edwards AFB CA | 93524-7048 | | | | |
| O CRONCORING (MA | DUITODING ACENCY | IAME(C) AND ADDDEC | C/EC) | | 10. SPONSOR/MONITOR'S |
| 9. SPONSORING / MC | JNITORING AGENCY I | IAME(S) AND ADDRES | 3(E3) | | ACRONYM(S) |
| Air Force Research | Laboratory (AFMC) | | | L | , |
| AFRL/PRS | | | | | 11. SPONSOR/MONITOR'S |
| 5 Pollux Drive Edwards AFB CA 9 | 2524 7049 | | | | NUMBER(S) |
| | | | | | Please see attack |
| 12. DISTRIBUTION / AVAILABILITY STATEMENT | | | | | |
| Approved for public release; distribution unlimited. | | | | | |
| 13. SUPPLEMENTARY NOTES | | | | | |
| | | | | | |
| 14. ABSTRACT | | 100,000 | | | |
| | | | | • | |
| | | | | | |
| | | | | | |
| | | | | | • |
| | | | | | |
| | | | 7 . | $\Lambda\Lambda Z \Gamma$ | ነለኃለ ለስፍ |
| | | | | UUSL | 1129 105 |
| | | | - | ••• | , |
| 45 AVE | | | | | |
| 15. SUBJECT TERMS | | | | | · . |
| 40 orollowica in | NEIO ATION OF | | 47 LIBETATION | 10 1000 | D 100 NAME OF DECRONORS |
| 16. SECURITY CLASSIFICATION OF: 17. LIMITATION 18. NUMB OF ABSTRACT OF PAGES | | | | | |
| ···· | | | | | Leilani Richardson |
| a. REPORT | b. ABSTRACT | c. THIS PAGE | $\left(\begin{array}{c} A \end{array}\right)$ | | 19b. TELEPHONE NUMBER (include area code) |
| Unclassified | Unclassified | Unclassified | | | (661) 275-5015 |

920° MIGS

MEMORANDUM FOR PRS (In-House/Contractor Publication)

FROM: PROI (STINFO)

08 Mar 2001

SUBJECT: Authorization for Release of Technical Information, Control Number: AFRL-PR-ED-TP-2001-048

Liu, C.T., "Investigating Near Tip Damage and Crack Growth Behavior in a Solid Propellant"

(VuGraphs)

JANNAF 34th Structures & Mechanical Behavior Subcommittee Meeting (Cocoa Beach, FL, 26-30 Mar 2001) (Deadline: 09 Mar 2001)

(Statement A)

and Crack Growth Behavior in a Investigating Near Tip Damage **Solid Propellant**

Dr. C. T. Liu

Principal Materials Research Engineer


Air Force Research Laboratory



Objectives


- Investigate the Local Damage Mechanisms Near the Crack tip in a Solid Propellant.
- Investigate the Effects of Local Damage on the Crack Growth Behavior under a Constant Strain Rate Condition.








Specimen Geometry

Crack Tip Profiles















Crack Tip Profiles














Damage Zone at Crack Tip








Crack Tip Damage Model



Highly Damaged Zone


TKLRLT - COD vs. Time






TKLRLT - Failure Process Zone vs.











Figure Critical stress intensity factor versus specimen thickness.



Distance From specimen center/specimen thickness

Figure Damage variation along the thickness of the specimen as a function of the applied strain.




Figure Crack growth rate versus time.



Conclusions



- The fracture toughness for the onset of crack growth is insensitive to the variation of the thickness of the specimen.
- Three-dimensional micro-macro damage analyses the crack front, resulting in a straight crack front. reveal that damage distribution is uniform along
- The crack-damage interaction is a contributing factor to the fluctuation of the crack growth behavior.